

December 23, 2005, 2005

Mr. John Corey
Seamless Flooring Systems
321 E. Ship Creek Avenue
Anchorage, AK 99501

Re: Napaskiak Flooring, 20093.00

Dear Mr. Corey:

I inspected the washeteria and water treatment plant floors on December 22, 2005 along with Phillip Nicholai Jr. Tribal Administrator. I observed very noticeable arcing trowel marks in both the washeteria and water treatment plant. In some cases, the arc was filled with resin (with no aggregate at the surface). This was especially noticeable at the water treatment plant.

The trowel marks are especially noticeable in the common area of the washeteria (laundry area plus hall to bathrooms). The marks are also noticeable in the boiler room, large bathroom and water plant. They are not too bad in the office, dryer air room or small bathroom. I have enclosed some photos. The arcs are much more noticeable in person then in the photos.


In addition to the trowel marks there are many "pools" of finish resin without aggregate at the surface. There are also scattered protrusions (bumps) and globs of resin on the floor (see attached sketch).

The overall appearance is not uniform, is unattractive and does not look professionally done. In a few cases seams are showing through slightly and can use a little more touch-up. This work does not meet the quality standard we anticipated or the project specifications.

I observed the floor system at the Bethel airport for comparison. It had a uniform aggregate surface through out, although some color deviations were visible. In all it had a much more uniform surface characteristic.

Please return and make the flooring look uniform. All areas need repairs except the office, dryer room and small bathroom. We would like this done prior to January 14, 2006 if possible since the work crew returns then. We will not pay your invoice until we have a satisfactory product.

Sincerely,


Dave Yanoshek, Project Manager

CC: Phillip Nicholai, Jr. Tribal Administrator
Jim Patterson, VSW
Lee Olsen and Steve Munn, CRW

CRW ENGINEERING GROUP, LLC

3940 Arctic Blvd. • Suite 300
Anchorage, Alaska 99503
(907) 562-3252 Fax 561-2273


JOB _____

SHEET NO. _____ OF _____

CALCULATED BY _____ DATE _____

CHECKED BY _____ DATE _____







SCALE _____



water
plant


Barre

wildcat



Pool
old & missing
wall

Globs



Napaskiak water
plant